

Bradford Prescott
Photographs from April 3, 2013 Inspection



Photograph 1 – Panoramic; facing Northeast – View of reservoir from southwest corner.



Photograph 2 – Facing North – View of northwestern corner of reservoir with floating dock and boats in the foreground.



Photograph 3 – Facing South-Southeast – View of dam with shaded-dock in foreground.



Photograph 4 – Facing Southeast – View of downstream side of dam.



Photograph 5 – Facing East-Southeast – View of floating dock and boats with view of eastern section of reservoir and surrounding hills.



Photograph 6 – Facing North – View of spillway; spillway was spilling over at time of inspection.

Photograph 8 – Facing North – View showing upstream channels located on the north side of the reservoir.



Photograph 7 – The downstream channel was flowing during the inspection.





Photograph 9 – Facing South-Southeast – View from upstream channels in previous photograph looking towards the reservoir.

